

















BRICK GRILL BASEMENT



Brick Grill Basement B1 - looking along Smelt culvert wall.



Brick Grill Basement B2 - looking along Smelt culvert wall.



Brick Grill Basement B3 - looking at existing block foundation wall along culvert.

BRICK GRILL BASEMENT



Brick Grill Basement B4 - looking along block foundation wall along culvert.



Brick Grill Basement B5 - looking towards Commercial Street along culvert wall.



Brick Grill Basement B6 - looking at NW corner at Commercial Street.

BRICK GRILL BASEMENT



Brick Grill Basement B7 - looking east along foundation wall
between Chair Fair Building.

MORANTE INSURANCE/BARBER SHOP BASEMENT



Morante Insurance/Barber Shop Basement M1 - looking in SW corner at culvert wall.



Morante Insurance/Barber Shop Basement M2 - looking at SW corner at slab wall interface.



Morante Insurance/Barber Shop Basement M3 - looking east.

MORANTE INSURANCE/BARBER SHOP BASEMENT



Morante Insurance/Barber Shop Basement M4 - looking at basement wall along culvert.



Morante Insurance/Barber Shop Basement M5 - another view at basement wall along culvert.



Morante Insurance/Barber Shop Basement M6 - view showing significant settlement of basement wall and concrete cap.

MORANTE INSURANCE/BARBER SHOP BASEMENT



Morante Insurance/Barber Shop Basement M7 - view along culvert wall showing separation of slab and wall.



Morante Insurance/Barber Shop Basement M8 - another view showing settlement.



Morante Insurance/Barber Shop Basement M9 - view looking west.

MORANTE INSURANCE/BARBER SHOP BASEMENT



Morante Insurance/Barber Shop Basement M10 - view showing steel beam framing of floor above.



Morante Insurance/Barber Shop Basement M11 - view shows settlement of soil in basement.



Morante Insurance/Barber Shop Basement M12 - another view in SE corner showing framing.

MORANTE INSURANCE/BARBER **SHOP BASEMENT**



Morante Insurance/Barber Shop Basement M13 - framing in NE corner.



Smelt Brook 1 - looking toward Commercial Street.



Smelt Brook 2 - looking toward Commercial Street at culvert's south stone wall.



Smelt Brook 3 - looking east at 72 inch pipe beneath concrete slab.



Smelt Brook 4 - view of stone foundation below concrete wall along north side of culvert.



Smelt Brook 5 - view showing undermining along north culvert stone wall.



Smelt Brook 6 - another view along north wall.



Smelt Brook 7 - looking toward Commercial Street below timber decking.



Smelt Brook 8 - looking away from Commercial Street at Morante Insurance Building floor framing.



Smelt Brook 9 - view of deteriorated steel floor framing above culvert.



Smelt Brook 10 - another view looking toward Commercial Street of floor framing above culvert.



Smelt Brook 11 - view looking at additional steel floor framing.



Smelt Brook 12 - view looking toward Commercial Street at framing above culvert.



Smelt Brook 13 - looking toward Commercial Street at narrow section of culvert below building.



Smelt Brook 14 - view looking toward Commercial Street showing movement at culvert walls.



Smelt Brook 15 - another view towards Commercial Street at narrow culvert section.



Smelt Brook 16 - view of southern culvert wall sections.



Smelt Brook 17 - view looking away from Commercial Street showing cracked and settled wall.



Smelt Brook 18 - view looking away from Commercial Street at undermined wall section below.



Smelt Brook 19 - looking away from Commercial Street at floor framing above.



Smelt Brook 20 - view looking away from Commercial Street.



Smelt Brook 21 - another view looking away from Commercial Street at floor framing.



Smelt Brook 22 - another view of floor framing looking away from Commercial Street.



Smelt Brook 23 - looking at the edge of Commercial Street.



Smelt Brook 24 - looking at the edge of Commercial Street.



Smelt Brook 25 - view looking at edge of Commercial Street.



Smelt Brook 26 - view of reinforced concrete slab at Commercial Street sidewalk showing significant deterioration.



Smelt Brook 27 - view of reinforced concrete slab at Commercial Street sidewalk showing significant cracks.



Smelt Brook 28 - view of reinforced concrete slab at Commercial Street sidewalk showing significant cracks.



Smelt Brook 29 - view of reinforced concrete slab at Commercial Street sidewalk showing significant cracks.



Smelt Brook 30 - view of reinforced concrete slab at Commercial Street sidewalk showing significant cracks.



Smelt Brook 31 - view of reinforced concrete slab at Commercial Street sidewalk showing significant deterioration.



Smelt Brook 32- view below Commercial Street at pipe penetration at wall.



Smelt Brook 33 - view below Commercial Street.



Smelt Brook 34 - view below Commercial Street along south side.



Smelt Brook 35 - view below Commercial Street at center pier.



Smelt Brook 36 - view below Commercial Street along north side.

BUILDING EXTERIOR



Brick Grill Exterior E1 - front view.



Brick Grill Exterior E2 - view at rear patio.



Brick Grill Exterior E3 - from patio looking west.

BUILDING EXTERIOR



Brick Grill Exterior E4 - from patio looking west.



Brick Grill Exterior E5 - from patio looking north.



Brick Grill Exterior E6 - from patio looking south at Chair Fair Building.

BUILDING EXTERIOR



Brick Grill Exterior E7 - from patio looking at Chair Fair Building.



Brick Grill Exterior E8 - looking at bulkhead entrance.



Brick Grill Exterior E9 - looking east at Chair Fair Building.

BUILDING EXTERIOR



Brick Grill Exterior E10 - roof view looking north over Morante Insurance Building.



Brick Grill Exterior E11 - looking NW over Morante Insurance Barber Shop.



Brick Grill Exterior E12 - looking towards Commercial Street over Morante Insurance Barber Shop.

BUILDING EXTERIOR



Brick Grill Exterior E13 - looking toward Commercial Street over 1 story section.



Brick Grill Exterior E14 - looking south from Morante Insurance at Brick Grill.



Brick Grill Exterior E15 - looking west from Morante Insurance at Brick Grill.

BUILDING EXTERIOR



Brick Grill Exterior E16 - looking east along side of Brick Grill.