
Town of Weymouth Massachusetts

Robert L. Hedlund Mayor

75 Middle Street Weymouth, MA 02189







2021 AP

Fax: 781.335.8184

TTY: 781.331.5124

MEMORANDUM

#21 055

TO:

TOWN COUNCIL

FROM:

ROBERT L. HEDLUND, MAYOR

RE:

COMMUNITY PRESERVATION FUND TRANSFER FOR THE

PRESERVATION OF THE FIRST CHUCH

DATE:

APRIL 1, 2021

I hereby submit the following measure to Town Council for its consideration and action:

"That the Town of Weymouth transfer the sum of \$178,738.00 from the Community Preservation Historic Resources Fund (4906-321005) and \$254,262 from the Community Preservation Unreserved Fund (4906-321001), for a total of \$433,000.00, for historic architectural services for the restoration and preservation of the exterior of First Church as approved by the Community Preservation Committee."

This measure requires a legal notice and public hearing.

At the time of this submittal, the Community Preservation Historic Resources Fund balance is \$178,738.00; and the Community Preservation Unreserved Fund balance is \$1,722,556.69.

Reformal Die	PH Dto.	
Comm. Referral	TC Vote	
Comm. Vote	TC Vote Dte	
Comm. Vote Dte	Town County	72 PR -1 M 00 32

Department of Planning and Community Development

Robert J. Luongo
Director of Planning and
Community Development
email: rluongo@weymouth.ma.us
(781) 340-5015

Town of Weymouth Massachusetts



Robert L. Hedlund Mayor

75 Middle Street Weymouth, MA 02189

www.weymouth.ma.us

MEMORANDUM

TO:

Robert L. Hedlund, Mayor

FROM:

Robert Luongo, Director of Planning & Community Development

DATE:

April 1, 2021

SUBJECT:

Request for Funding - CPA

At the March 4, 2021 meeting of the Community Preservation Committee, the committee reviewed and discussed the application put forward by First Church in the amount of \$433,000. Thomas Wilburn, presented the request for the restoration and preservation of the exterior of the church. The funds will be used to contract with McKinnell McKinnell & Taylor of Norwell and a contractor. McKinnell McKinnell & Taylor specializes in historic architecture. The firm will develop biddable plans, specifications and oversee the work. Previously, McKinnell McKinnell & Taylor performed some investigative work on the condition of the building and prepared a report. The report includes a cost estimate to restore the exterior. This request is based on the investigative report. First Church is excited to get this project underway in anticipation of Wcymouth's 400th anniversary.

After review and discussion, the following motion was approved unanimously.

Motion to appropriate and fund \$433,000 for historic architectural services for the restoration and preservation of the exterior of First Church - \$178,739 from the historic resources fund balance account 4906-321005 and \$254,262 from the unreserved fund balance account 4906-321001.

The Community Preservation Committee appreciates your review and action on this recommendation.

ATTACHMENT:

Funding Request submitted by First Church dated February 23, 2021

CC:

Patricia Cook, Town Accountant Christopher Hannan, Chairman, CPC

WEYMOUTH

Community Preservation Committee Application for Funding

Name THOMAS WILBURN Date FEB. 23, 2021 Phone 339-188-0249 Email HOMASL WILBURN & GMAIL. COM Address 17 CHURCH St., WEYMOUTH, LAA Affiliation/Organization (if applicable) FIRST CHURCH IN WEYMOUTH Project Name: \$433,000
Purpose (please select all that apply)
Historic Preservation Open Space & Recreation
Description Please provide a written narrative with detailed data; including cost estimates, schedule, budget, maintenance plan, if any and implementation strategy. Include other funding sources and the amounts of funding. Attach separate sheets as needed. **PLEASE SEE ** ATTACHMENT** " WISTIGHT CUBLET **HISTORY PLEASED FLEST STREET WISTIGHT PRED NEED **DESCRIBE HOWELL, MCKINGELL & FAYLOR, INC. " JAN. 19, 2021 Describe how this this project helps to preserve Weymouth's character. Please provide a written narrative including the goals of the project, who benefits, and how the project relates to planning documents such as the Town's Master Plan. Describe the nature of support and outreach for the project. Attach separate sheets as needed. **PLEASE SEE ** ATTACH MENT** 2
Applicants are encouraged to be creative and consider projects that will benefit the community; including, but not limited to; projects which may not receive typical funding from traditional sources. ATRIVIDUALLY, FIRST CHUTCH IS CLUSTED & 30,000.— to this projects which may not receive typical funding from traditional sources. ATRIVIDUALLY, FIRST CHUTCH IS CLUSTED & 30,000.— to this projects which may not receive typical funding from traditional sources. ATRIVIDUALLY, FIRST CHUTCH IS CLUSTED OFF SET THE CONSTITUTION Submit to: Community Preservation Community Development TO DAY FOR UNEXPECTED TO Middle Street, Weymouth, MA 02189 January 1, 2007

INVESTIGATIVE SURVEY

PROJECT

Historic Restoration The First Church Weymouth, MA A/E Project No. 20028.00

EXECUTIVE SUMMARY

McKinnell McKinnell & Taylor Inc. (MMT) was commissioned to investigate the exterior envelope detailing the front elevation of The First Church located at 17 Church Street in Weymouth, Massachusetts. MMT visited the site on June 5, 2020 and December 2, 2020. Kate Marshall from the Town of Weymouth and Tom Wilburn representing the Church were present at the first meeting to discuss the focus of the survey. Tom Wilburn was present at the second meeting, where Tully Construction and MMT performed destructive demolition to investigate the original materials beneath the vinyl coverings. Environmental Hygienist, TRC Companies performed an additional survey and tests in support of this investigation.

HISTORIC BACKGROUND

In 2000 the historic structure application for The First Church was recorded at the Massachusetts Historic Commission (MHC) historic record MHC 310, 1833, see the appendix for full copy of the record.

In the 2010 the district The First Church resides in was recommended for inclusion in the National Register of Historic Places via the Massachusetts Historic Commission. See appendix for cover transmittal of the application/recommendation for the Weymouth Meeting House Historic District and the site plan marking the boundary. The significance of this document and the place Weymouth holds in the history of the original colonization and separation from England, is clearly identified. As one of the oldest settlements and thereby one of the oldest Townships, Weymouth holds a considerable amount of historical significance.

Excerpts of the MHC record for the structure:

The First Church in Weymouth on Church Street is an austere, one-and-half story Greek Revival religious building constructed in 1833 at the crest of a hill on the north side of Church Street. The building has a T-shaped plan and a gable roof with a boxy bell tower emerging from the front gable end. This four-sided tower has triple pilasters at each corner and is topped by an octagonal cupola with compass weathervane. The shallowly projecting central entrance is articulated by four squared pilasters and a pediment with a fanlight. Three windows with eight-over-eight sash are arranged symmetrically above three paneled doors. The sides of the church feature double-height, eight-over-eight,

paired windows. A brick chimney rises from the slope of the roof, and there is a onestory, flat-roofed addition to the rear of the building. Set on granite foundations and clad in synthetic siding, the building is in good condition. It underwent major renovations in the early 1920s and 1954.

EXISTING CONDITIONS

The current building at 17 Church Street was constructed in 1833 and has undergone periodic renovations over the years. The renovation of 1953–1955 being the most impactful, where the building was lifted and moved back (to allow for Town construction at the road in front of the building and modifications in the basement for church activities). The new foundation, a cast-in-place concrete wall, replaced the original granite foundation. This renovation impacted the height of the entry from the ground requiring more steps to access the three front entry doors. Refer to the attached Survey Photos (SP) SP-1 thru SP-3.

By the time of the application of Historic Structures to MHC in the year 2000, the building was already clad in synthetic siding. Ten years later, additional coverings were added to the pilasters and other trim prior to the application of historic places in 2010. Refer to SP-4 thru SP-6.

The investigation of the existing materials included removing both vinyl siding and flashing, as well as PVC board coverings to get down to the original wood detailing beneath. The destructive demolition occurred at the southwest front entry door, at the roof line above the door, and at the eave to roof line of the main building. Refer to the attached photos SP-7 thru SP-25.

The original wood detailing was found to be in good condition. Although covered in deteriorated lead paint, the wood is solid and for the most part does not contain rot. Many of the trim transition pieces were removed when the aluminum flashing and vinyl siding was added to the building; this is likely because these pieces were hard to flash over. Recreating these pieces of wood will require some further investigation with historic photos of the Church prior to the installation of the vinyl siding.

The areas where the wood has suffered from rot are generally found at the base of the building, both where the building hits the entry slab and where the pilasters meet the foundation. In these areas, a combination of wood repair and replacement will need to be considered.

The Environmental Hygienist took samples of the paint and sealants for lead and asbestos impacts on the project. Refer to the appendix for the attached report from TRC.

RECOMMENDATIONS

During the preliminary meeting with the Church representative and the Town representative, it was determined that the initial investigation would focus on the historic restoration of the front elevation. The historic restoration recommendations that follow are based on that investigation:

- Original Wood Detailing: Remove synthetic covering, PVC trim and metal
 flashing, abate existing paints to bare wood, repair where necessary and paint as
 required. Maintain the existing wood trim that is old growth wood.
 Characteristically the wood has tight grain, which makes it naturally able to resist
 rot and generally outperform any new replacement wood product. Woods
 available today are new growth with wide grain patterns that absorb water and rot
 easily.
- 2. Original Clapboard Siding: Remove the synthetic covering and existing cedar siding to the sheathing and replace with new cedar siding to replicate the 3.5" to weather, with a beveled edge, painted. Although the siding was found to be generally in good condition, it is covered in deteriorated lead paint, and the process of stripping the cedar of lead paint can have inconsistent results.
- 3. Front Entry Doors: Maintain the recently replaced front entry doors while restoring the trim around the doors to original conditions.
- 4. Bell Tower: Maintain the synthetic siding on the Bell Tower as it is difficult to access, and the recent work done in this area is in good condition and required to conceal the cell tower equipment inside.
- Half Round Attic Window: Restore glass and glazing, protect with new clear glass storm window.
- Electrical: Miscellaneous work associated with removing and reinstalling existing light fixtures. There is a lighting protection system that protects the Bell Tower that needs to be resecured to the building.

COST ANALYSIS

The cost is presented in two summaries. The first cost as initially requested is for the historic restoration of the front elevation for the Church to seek Community Preservation Act (CPA) funding thru the Community Preservation Committee. The second cost has been requested by the Church to pursue the restoration of all of the facades and is based on the costing for the front elevation with multipliers to estimate the entire building. Both costs include design fees for MMT to bring the drawings to a level for bid purposes and to perform limited Construction Administration of the work. There is an economy of scale for MMT to provide design services for the entire building. The costing at this phase is generalized and a 10% contingency is carried to cover those items in which we have yet to investigate. Refer to the attached cost estimates for details.

The total sum of restoration front elevation only:

\$152,100.00

The total sum of restoration entire building*:

\$433,000.00

*deduct alternate change cedar siding to Hardie plank +/- (\$15,000 to \$20,000)

MCKINNELL MCKINNELL & TAYLOR INC.

164 WASHINGTON STREET - STE 201

NORWELL, MA 02061 TEL: 781-878-6223

FAX: 781-878-8920

PROJECT NAME: CLIENT: 1/19/21

GPT

DATE: BY:

PROJECT LOCATION: A/E PROJECT NO.:

The First Church 17 Church Street, Weymouth, MA

Historic Restoration 20028.00

ENE	ITEM DESCRIPTION	FINIT	220	MATE	MATERIALS	LAB	LABOR	
2			,	UNIT COST	AMOUNT	UNIT COST	AMOUNT	TOTAL COST
	ARCHITECTURAL							294,500.00
	El ECTBICAL							
								10,000.00
	SUBTOTAL							00 001
								304,300.00
	20% OVERHEAD AND PROFIT							60.900.00
	SIBTOTAL							
	SOBIOLAL							365,400.00
	CONSTRUCTION ESTIMATE							00 007 .100
								302,400.00
	10% CONTINGENCY							36,540.00
	A/C East for Design and O/A							
	AE ree tot Design and C/A							31,050.00
	TOTAL							
								432,990.00
	CONSTRUCTION BUDGET							
								433,000.00
	CONSTRUCTION DURATION DAYS							
			The second second second					

- PAGE 2 of 3

MCKINNELL MCKINNELL & TAYLOR INC.

164 WASHINGTON STREET - STE 201 NORWELL, MA 02061 TEL: 781-878-6223 FAX: 781-878-8920

DATE: BY:

The First Church	17 Church Street, Weymouth, MA	Historic Restoration	20028.00	
CLIENT:	PROJECT LOCATION:		1/19/21 A/E PROJECT NO.:	GPT

LINE	NOIFEIGORAGE MATE	Ī	À	MATERIALS	NALS	LABOR	OR	
2		5	,	UNIT COST	AMOUNT	UNIT COST	AMOUNT	TOTAL COST
1	ARCHITECTURAL							
	General Conditions							
3	Permit Fees \$10/\$1000	LS	-					2,900,00
4	Mobilization and Closeout	rs	-					2,500.00
	Adjust rough estimate for take-offs	LS	-					25,000.00
ဖ	Division 2 - Demolition							
7	Asbestos Abatement	rs S	-	800.00	800.00	1,400.00	1.400.00	2.200.00
	Remove synthetic coverings - two layers	SF	4690			1.60	7,504.00	7.504.00
6	Repair Class Type I - Paint removal (lead paint)	SF	1150	20.00	23,000.00	40.00	46.000.00	69,000,00
10								
11	Division 5 - Miscellaneous Metals							
12	HC Ramp Railing - Wrought Iron	느	100	200.00	20,000.00	65.00	6,500.00	26.500.00
13	Division 6 - Carpentry							
14	Restore Half Round Window	SF	12	40.00	480.00	85.00	1,020.00	1.500.00
15	Carpentry Repair Class II and III	rs S	-	8,000.00	8,000.00	40,000.00	40,000.00	48,000.00
16	Finish Carpentry	rs	1	6,250.00	6,250:00	18,750.00	18,750.00	25,000.00
17	Division 7 - Waterproofing							
18	New Clapboard Siding (25% waste)	SF	3500	2.00	17,500.00	3.00	10,500.00	28,000.00
19	Siding Starter	LF	300	0.50	150.00	2.67	801.00	951.00
20	Building Wrap (Drain Wrap)	SQ	35	12.00	420.00	20.00	700.00	-
21	Sealants	LS	1	200.00	200.00	1,000.00	1,000.00	,
	Division 8 - Windows			,				
23	Storm window at Arch window	E	25	450.00	11.250.00	400.00	10.000.00	21 250 00
24	Division 9 - Painting							20.0041
П	Preparation	LS	-	1,250.00	1,250.00	2,500.00	2.500.00	3.750.00
	Paint at new Siding (2 coats)	SF	3500	1.50	5,250.00	3.00	10,500,00	15,750,00
	Paint at comers, brackets, carpentry detailing	SF	1150	2:00	2.300.00	8.50	9 775 00	12 075 00
								2000
T	SUBTOTAL							294 500 00
30								

- PAGE 3 of 3

MCKINNELL MCKINNELL & TAYLOR INC.

164 WASHINGTON STREET - STE 201 NORWELL, MA 02061

TEL: 781-878-6223

FAX: 781-878-8920

1/19/21 GPT

DATE: BY:

PROJECT LOCATION: PROJECT NAME: A/E PROJECT NO.: CLIENT:

The First Church 17 Church Street, Weymouth, MA toration

Historic Rest	20028.00
	Historic Rest

LINE	ITEM DESCRIPTION	FIRST	1	MAT	MATERIALS	V	ABOR	
2		5	3	UNIT COST	TAILONA	TOOO TIMIL		TOTAL COST
-	ELECTRICAL				NOOM	ONI COSI	AMOUNT	
2								
П	Demolition							
	Disconnect and Make Safe	LS.	-			3 750 00		0
2						2,7 30.00	00.007,6	3,750.00
	New Work							
	Resecure Lightning Protection	LS	-			8 250 00		0000
8						0,230.00	00.002,0	6,250.00
6								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
	SUBTOTAL							
59								10,000.00
30								

Attachment #2

The First Church of Weymouth has been an integral part of the long history of the Town of Weymouth. For one hundred years, until 1723 with the establishment of a second meetinghouse in the southern part of town, the First Church in Weymouth and the Town of Weymouth were essentially synonymous; the church records were the town's records and vice versa. The church served as a house of worship and town hall since both the religious and civic affairs of the town were meshed.

Establishing a meeting house was a priority when the settlement of Wessagusset was repopulated in the summer of 1623 by the Gorges party. Two ministers arrived with the expedition to establish a permanent colony. History records that the first meetinghouse stood on Watch Hill, now known as North Cernetery. Subsequent replacements were built on Church Street, one during Samuel Torrey's tenure (1665-1707) and a second completed in 1753 after three barrels of gunpowder stored in the loft exploded and started a fire that consumed the building. The third and present structure erected in 1833 has continued the unbroken tradition of serving the needs of its parishioners as well as being good citizens of the town for the last 187 years.

Many historic events and notable people are connected to the history of First Church. William Smith served as minister for forty-nine years (1734-1783.) He read the Declaration of Independence from the pulpit to the town in 1775. He performed the baptism and the marriage of his daughter Abigail to John Adams. Abigail Adams, wife of the second president of the United States and mother of John Quincy Adams, the nation's sixth president, is undoubtedly the most famous personality to have lived in Weymouth. She has become one of the country's most famous First Ladies and grew up in First Church. In recognition of the part she played in history, The National Park Service established the Weymouth Meeting House Historic District in 2010 which includes the Abigail Adams House and First Church. The Adams National Park in Quincy now includes this district in its literature and encourages visitors.

First Church is deeply embedded in the history of Weymouth and its residents. There is a tong-standing partnership with The Friends of the Homeless which has shelters in the town and we provide monthly meals to Father Bill's in Quincy. Civic groups like the Boy Scouts and AA have long used the facilities. Recently we have become the home of the Weymouth Food Pantry.

The congregation is dedicated to carrying on its missions and is eagerly anticipating the celebration of the 400th anniversary of its gathering.